

# Certificate of Accreditation



## Casa Environmental Services Ltd

Testing Laboratory No. 7914

**Is accredited in accordance with International Standard ISO/IEC 17025:2017  
– General Requirements for the competence of testing and calibration  
laboratories.**

This accreditation demonstrates technical competence for a defined scope specified in the schedule to this certificate, and the operation of a management system (refer joint ISO-ILAC-IAF Communiqué dated April 2017). The schedule to this certificate is an essential accreditation document and from time to time may be revised and reissued.

The most recent issue of the schedule of accreditation, which bears the same accreditation number as this certificate, is available from [www.ukas.com](http://www.ukas.com).

This accreditation is subject to continuing conformity with United Kingdom Accreditation Service requirements.

A handwritten signature in black ink, reading "Matt Gantley", is positioned above a horizontal line.

**Matt Gantley**, *Chief Executive Officer*  
United Kingdom Accreditation Service

Initial Accreditation: 5 February 2014  
Certificate Issued: 25 January 2021



Scan QR Code to  
verify

# Schedule of Accreditation

issued by

## United Kingdom Accreditation Service

2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

 <b>7914</b>  Accredited to <b>ISO/IEC 17025:2017</b>	<b>Casa Environmental Services Ltd</b>	
	<b>Issue No:</b> 007 <b>Issue date:</b> 16 November 2022	
	<b>The Haybarn</b> Londonderry Farm Keynsham Road Willsbridge Bristol BS30 6EL United Kingdom	<b>Contact: Mr Ben House</b> <b>Tel:</b> +44 (0) 1179 322 323 <b>E-Mail:</b> <a href="mailto:benhouse@casaenvironmental.co.uk">benhouse@casaenvironmental.co.uk</a> <b>Website:</b> <a href="http://www.casaenvironmental.co.uk">www.casaenvironmental.co.uk</a>
Testing performed by the Organisation at the locations specified below		

### Locations covered by the organisation and their relevant activities

#### Laboratory locations:

Location details		Activity	Location code
<b>Address</b>  The Haybarn Londonderry Farm Keynsham Road Willsbridge Bristol BS30 6EL United Kingdom	<b>Local contact</b>  Contact: Mr Ben House Tel: +44 (0) 1179 322 323 EMail: <a href="mailto:benhouse@casaenvironmental.co.uk">benhouse@casaenvironmental.co.uk</a>	Health and Hygiene  Asbestos – All Support Functions	A

#### Site activities performed away from the locations listed above:

Location details	Activity	Location code
Client Premises	Health and Hygiene	B
Mobile laboratories	Health and Hygiene	C



7914  
Accredited to  
ISO/IEC 17025:2017

**Schedule of Accreditation**  
issued by  
**United Kingdom Accreditation Service**  
2 Pine Trees, Chertsey Lane, Staines-upon-Thames, TW18 3HR, UK

**Casa Environmental Services Ltd**

**Issue No: 007 Issue date: 16 November 2022**

Testing performed by the Organisation at the locations specified

DETAIL OF ACCREDITATION

Materials/Products tested	Type of test/Properties measured/Range of measurement	Standard specifications/ Equipment/Techniques used	Location Code
ASBESTOS FIBRES IN AIR	<u>Health and Hygiene</u>	Health and Safety Executive - Asbestos: The Analysts' Guide (HSG 248) – 2021	
	Sampling of air for fibre counting	Documented In-House Method TP04 based on HSG 248	B
	Fibre counting	Documented In-House Method TP04, Membrane Filter Method using Phase Contrast Microscopy (PCM) based on HSG 248	A, B, C
ASBESTOS IN BULK MATERIALS including materials and products suspected of containing asbestos	4 Stage Clearance Process	Documented In-House Method TP04, Membrane Filter Method using Phase Contrast Microscopy (PCM) based on HSG 248	B
	Sampling of bulk materials for asbestos identification	Documented In-House Method TP01 based on HSG 248	B
	Identification of: Amosite Chrysotile Crocidolite Fibrous Actinolite Fibrous Anthophyllite Fibrous Tremolite	Documented In-House Method TP01 using stereo-microscopy, polarised light optical microscopy and dispersion staining based on HSG 248	A
END			